




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)



ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)



ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




دیجیتال خودرو
شرکت دیجیتال خودرو سامانه (مسئولیت محدود)


اولین سامانه دیجیتال تعمیرکاران خودرو در ایران




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)









ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)



ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)

A64
Black




90980-12686

A71
White




90980-12372

A72
White




90980-12372

A73
Blue




90980-12372

B3
Black




90980-11858

B28
Black




90980-12611


ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




90980-11016



90980-12362




90980-12974



90980-12398


ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)

B77
Black




90980-12836

B88
Black












90980-12353

B93
Black







90980-12A38





ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)




ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)



90980-12887




90980-12890



90980-12771

90980-12770



90980-12741

90980-12740

ABS (w/ VSC) (Before Oct. 2015 Production), Auto LSD (Before Oct. 2015 Production), Downhill Assist Control (Before Oct. 2015 Production), Hill-Start Assist Control (Before Oct. 2015 Production), TRC (Before Oct. 2015 Production), VSC (Before Oct. 2015 Production)

